DISCIPLINE: Hardware— Switches & Routers Discipline Roadmap for: Switches & Routers

Current 2 Years		5 Yea	5 Years		
Baseline Environment Switches 3COM switches 6506 Switch Cisco Switches catalyst (2916, 2924, 4003, 4006, 6513, 3550) DMV Core Switches Avaya Nortel Accelar 1150R-B HP Nortel Switches (350,450) Enterasys	Tactical Deployment Cisco Nortel Enterasys HP			Strategic Direction Market Watch	
Routers 6506 Switch/Router Cisco 4000 Routers Cisco Routers (1650,2500, 2600, 2620, 3660, 3600, 1750, DSL Cisco 840) Nortel ARNs	Cisco Nortel Enterasys HP		Shared ✓	Agency √	
Retirement Targets	Mainstream Platforms (must be su Cisco, Nortel, Enterasys, HP	uppo	orted)		
Containment Targets		Emerging Platforms			
3COM, Avaya					
Implications and Dependencies Only select from products that support indus	stry standards.				
				_	
Roadmap Notes		==			

DISCIPLINE: Hardware— Switches & Routers (Cont'd) Discipline Roadmap for: Switches & Routers

- Discipline Boundaries:
 - Equipment room, MDF-IDF equipment. Only wiring closets.
- Discipline Standards:
 - IETF routing standards.
- Migration Considerations:
 - □ TBD
- Exception Considerations:
 - □ TBD
- Miscellaneous Notes:
 - None.
- Established Date
 - October 16, 2003
- Date Last Updated:
 - □ July 25, 2007
- Next Review Date:
 - □ July 2008